

IMPEX SYSTEMS INC.

52, SHAMARAJ IYENGAR ROAD, BASAVANAGUDI, BANGALORE-560 004
TELEFAX : 080-26670289 Mobile : Sales & Service : 98451 33736
E-mail : impexsys@gmail.com

TAX-INVOICE




ID No: KR03A0144994

State Code	2	9	Original for Recipient
			Duplicate for Supplier/Transporter
			Triplicate for Supplier
Reverse Charge	:		Transportation Mode : Road
TAX-INVOICE No	:	032/SER/25-26	Vehicle Number :
TAX-INVOICE Date	:	11.07.2025	Date of Supply : 11.07.2025
State	:	Karnataka	Place of Supply : Bangalore
Details of Receiver Billed to:			Details of Consignee Shipped to:
Name	:	M/s R V INSTITUTE OF MANAGEMENT,	Name : R V INSTITUTE OF MANAGEMENT
Address	:	CA -17, 36th Cross, 26th Main, 4th 'T' Block Jayanagar, BANGALORE - 560041	Del. Address : CA -17, 36th Cross, 26th Main, 4th 'T' Block Jayanagar, BANGALORE - 560041
GSTIN (Party)	:	29AAATR0758A1ZP	GSTIN (Party) : 29AAATR0758A1ZP
State	:	Karnataka	State : Karnataka

S.No	Description of Items	HSN Code	UoM	Qty	Rate (INR)		Amount (INR)	
1	LG make 1.5 TR split ACs – Placement & Bd Room	995463	No	3	1,000	00	3,000	00
2	Onida make 1.5 TR Split ACs – Director's Office	995463	No	2	1,000	00	2,000	00
3	LG make 3.0 TR Ductable AC – Conference Hall	995463	No	1	1,950	00	1,950	00
4	LG make 8.5 TR Ductable AC – Conference Hall	995463	No	1	5,529	50	5,529	50
5	LG make 2.0 TR Split AC – Seminar Hall	995463	No	6	1,000	00	6,000	00
6	LG make 2.0 TR Split AC – Computer Labs	995463	No	6	1,000	00	6,000	00

(Items SIX only) P.O. No 33000017111/0 Dt 18.10.24 for AMC Charges covering period from 01.04.2025 to 30.09.2025

Total TAX-INVOICE Amount in Words:	Total Amount Before Tax	24,479	50
Rupees TWENTY EIGHT THOUSAND EIGHT HUNDRED & EIGHTY SIX ONLY	Add CGST@14%	0	0
	Add SGST@14%	0	0
	Add CGST@9%	2,203	15
	Add SGST@9%	2,203	15
	Add IGST	0	0
Our GSTIN : 29AGKPB6729K1ZZ	Tax Amount : GST	4,406	30
Our PAN : AGKPB6729K	Total Amount After Tax	28,886	00
	GST Payable on Reverse Charge		0

Bank Details: NAME : IMPEX SYSTEMS INC BANK : INDIAN OVERSEAS BANK, BRANCH : BASAVANGUDI BRANCH A/C No: 189702000000127 IFSC CODE: IOBA0001897	 Certified that the particulars given above are true and correct. For IMPEX SYSTEMS INC., For IMPEX SYSTEMS INC.  Proprietor
Terms and Conditions: 1. Payments to be made by cheque/Draft/RTGS-NEFT only. 2. All Disputes subject to Bangalore jurisdiction 3. Interest at 24% PA will be charged if not paid on due date 4. Goods once sold cannot be taken back or exchanged 5. Our responsibility ceases once goods have handed over to you.	

[E&OE]

Certified the bill for supply
system inc for AME charge
of Air-Conditioning for the year of
2024-25. this 2nd payment from
1.04.25 to 30.09.25.

S. W. J. J. J.
30/7/2025

Alice
Pt. verify of process
Approved

30/7

ASP Name & Address

IMPEX SYSTEMS INC.#52, Shamaraj Iyenger Road,
Basavanagudi, Bangalore - 560 004.
Mob : 9845133736**L.G. Electronics India Ltd.**

Call Center No.

Customer Name	AV 3M	Date of Receipt	13-5-2025
Customer's Address	Jaynagar 4th block	Call No./ Receipt No.	262
		Model No.	
Tel. No.		Serial No.	
Complaint	Not cooling	Date of Purchase	
		Purchased From	
M/C Status	IW	OW	AMC
Installed By	SSD	ASP	LOCAL

Job Done.

we changed 2 No of capacitor & 2 No of AC gas
fully charged now the 2 No of AC working in
a good condition

Egide Sign

Symptom Code	Defect/Cause Code	Repair Code
Used Part (if any)		In case of gas charging & comp. replacement
Part No.		
Quantity		Joint Number
Price		New comp. No.
T C R Amt./ No. / Date		Old comp. No.

Service Call	Yes	No	Inst allation Call	Yes	No
Eva. Coil Clean / Wash	☐	☐	Location WAC / ID / OD	☐	☐
Cond. Coil Clean / Wash	☐	☐	Slope	☐	☐
Air Filter Wash	☐	☐	MCB Rating OK	☐	☐
Blower & Fan Touching	☐	☐	Stabilizer Rating OK	☐	☐
Tube Touching (if any)	☐	☐	Physical Damage (if any)	☐	☐
Noise / Vibration (if any)	☐	☐	Earthing	☐	☐
Grill Fitment	☐	☐	Pipe Length b/w ID & OD	☐	☐
Electrical Connection	☐	☐	Noise / Vibration (if any)	☐	☐
Unit Clean	☐	☐	Water Leakage (if any)	☐	☐

Ampere.....A

Voltage.....V

Grill Temp.....°C

Return Air Temp.....°C

Location WAC / ID / OD

Slope

MCB Rating OK

Stabilizer Rating OK

Physical Damage (if any)

Earthing

Pipe Length b/w ID & OD

Noise / Vibration (if any)

Water Leakage (if any)

*Inst allation check sheet to be filled

*Call attended within 12hrs / 24hrs / 48hrs or more than 48hrs

Cust. Sign with seal

ASP Name & Address

IMPEX SYSTEMS INC.#52, Shamaraj Iyenger Road,
Basavanagudi, Bangalore - 560 004.
Mob : 9845133736**L.G. Electronics India Ltd.**

Call Center No.

Customer Name	SSNR + RVJM	Date of Receipt	7-1-2025
Customer's Address	Jayamangal, 4th block	Call No./ Receipt No.	150
		Model No.	
Tel. No.		Serial No.	
Complaint	General service	Date of Purchase	
		Purchased From	
Status	IW	OW	AMC
Installed By	SSD	ASP	LOCAL

Job Done

We serviced all the no of A.C 4 no of A.C had to be got fixed it is all working in a good condition

Engg. Sign

Symptom Code	Defect/Cause Code	Repair Code
Used Part (if any)		In case of gas charging & comp. replacement
Part No.		
Quantity		Joint Number
Price		New comp. No.
T C R Amt./ No. / Date		Old comp. No.

Service Call	Yes	No	Inst allation Call	Yes	No
Coil Clean / Wash	☐	☐	Location WAC / ID / OD	☐	☐
Cond. Coil Clean / Wash	☐	☐	Slope	☐	☐
Air Filter Wash	☐	☐	MCB Rating OK	☐	☐
Blower & Fan Touching	☐	☐	Stabilizer Rating OK	☐	☐
Tube Touching (if any)	☐	☐	Physical Damage (if any)	☐	☐
Noise / Vibration (if any)	☐	☐	Earthing	☐	☐
Grill Fitment	☐	☐	Pipe Length b/w ID & OD	☐	☐
Electrical Connection	☐	☐	Noise / Vibration (if any)	☐	☐
Unit Clean	☐	☐	Water Leakage (if any)	☐	☐

Ampere.....A
Voltage.....V
Grill Temp.....°C
Return Air Temp.....°C

*Inst allation check sheet to be filled

*Call attended within 12hrs / 24hrs / 48hrs or more than 48hrs

Dust Sign with seal

ASP Name & Address

IMPEX SYSTEMS INC.#52, Shamaraj Iyenger Road,
Basavanagudi, Bangalore - 560 004.
Mob : 9845133736**L.G. Electronics India Ltd.**

Call Center No.

Customer Name	R.V.I.M	Date of Receipt	10/03/2025
Customer's Address	R.V.I.M Taya number 47 Vijaynagar	Call No./ Receipt No.	391
		Model No.	L-07
Tel. No.		Serial No.	
Complaint	4 NO AC Not working	Date of Purchase	
		Purchased From	
M/C Status	IW	OW	AMC ☒
		Installed By	SSD ASP LOCAL

Job Done: we have checking 4 NO AC
 3 NO AC old door pressure. other 2 NO
 gas charging and other 3 NO AC old
 door for gas charging
 Engg./Tech. Sign

Symptom Code	Defect/Cause Code	Repair Code
Used Part (if any)		In case of gas charging & comp. replacement
Part No.		
Quantity		Joint Number
Price		New comp. No.
T.C.R Amt./ No. / Date		Old comp. No.

Service Call		Yes	No	Installation Call		Yes	No
Eva. Coil Clean / Wash	☐	☐	Ampere.....A Voltage.....V Grill Temp.....°C Return Air Temp.....°C	Location WAC / ID / OD	☐	☐	
Cond. Coil Clean / Wash	☐	☐		Slope	☐	☐	
Air Filter Wash	☐	☐		MCB Rating OK	☐	☐	
Blower & Fan Touching	☐	☐		Stabilizer Rating OK	☐	☐	
Tube Touching (if any)	☐	☐		Physical Damage (if any)	☐	☐	
Noise / Vibration (if any)	☐	☐	Earthing	☐	☐		
Grill Fitment	☐	☐	Pipe Length b/w ID & OD	☐	☐		
Electrical Connection	☐	☐	Noise / Vibration (if any)	☐	☐		
Unit Clean	☐	☐	Water Leakage (if any)	☐	☐		

*Installation check sheet to be filled

*Call attended within 12hrs / 24hrs / 48hrs or more than 48hrs

Cust. Sign with seal